

序号	报告编号	发布日期	结论	影像资料
30	GX-B1312/20-P-25015	2025. 2. 11	所检项目合格。	
31	GX-B1312/20-P-25016	2025. 2. 12	所检项目合格。	
32	GX-B1547/20-P-25001~25003	2025. 2. 13	本次共检继电保护装置3部，3部继电保护装置所检项目合格。	

33	GX-B1547/20-P-25004~25006	2025. 2. 13	本次共检继电保护装置3部，3部继电保护装置所检项目合格。		
34	GX-B1547/20-P-25007~25008	2025. 2. 13	本次共检继电保护装置2部，2部继电保护装置所检项目合格。		
35	GX-B1547/20-P-25009	2025. 2. 13	所检项目合格。		

36	GX-B1337/22-P-25001~25005	2025. 2. 13	本次共检互感器 5组，5组互感器所 检项目合格。	 A photograph showing three technicians in a substation. Two are standing and one is kneeling, working on a large transformer. The date stamp '2025.1.19' is visible in the bottom right corner of the photo.
37	GX-B1337/22-P-25006~25009	2025. 2. 13	本次共检互感器 4组，4组互感器所 检项目合格。	 A photograph showing two technicians in a substation, standing and inspecting a large transformer. The date stamp '2025.1.24' is visible in the bottom left corner of the photo.
38	GX-B1319/21-P-25001~25003	2025. 2. 13	所检项目合格。	 A photograph showing three technicians in a substation. One is on a ladder, another is kneeling, and a third is standing, working on a transformer. The date stamp '2025.01.19' is visible in the bottom right corner of the photo.

39	GX-B1319/21-P-25004~25005	2025. 2. 13	所检项目合格。	
----	---------------------------	-------------	---------	---