

序号	报告编号	发布日期	结论	影像资料
158	GX-B1364/22-A-25478	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
159	GX-B1364/22-A-25479	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
160	GX-B1364/22-A-25480	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
161	GX-B1364/22-A-25481	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
162	GX-B1364/22-A-25482	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
163	GX-B1364/22-A-25483	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
164	GX-B1364/22-A-25484	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
165	GX-B1364/22-A-25485	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
166	GX-B1364/22-A-25486	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
167	GX-B1364/22-A-25487	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
168	GX-B1364/22-A-25488	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
169	GX-B1364/22-A-25489	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
170	GX-B1364/22-A-25490	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
171	GX-B1364/22-A-25491	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
172	GX-B1364/22-A-25492	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
173	GX-B1364/22-A-25493	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
174	GX-B1364/22-A-25494	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
175	GX-B1364/22-A-25522	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
176	GX-B1364/22-A-25523	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
177	GX-B1364/22-A-25525	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
178	GX-B1364/22-A-25526	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
179	GX-B1364/22-A-25527	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
180	GX-B1364/22-A-25528	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
181	GX-B1364/22-A-25529	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
182	GX-B1364/22-A-25530	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
183	GX-B1364/22-A-25524	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
184	GX-B1364/22-A-25519	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
185	GX-B1364/22-A-25516	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
186	GX-B1364/22-A-25531	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
187	GX-B1364/22-A-25515	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
188	GX-B1364/22-A-25520	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
189	GX-B1364/22-A-25521	2025/5/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
190	GX-B1364/22-A-25517	2025/5/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
191	GX-B1364/22-A-25518	2025/5/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
192	GX-B1509/20-A-25011	2025/5/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
193	GX-B1509/20-A-25012	2025/5/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
194	GX-B1509/20-A-25013	2025/5/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
195	GX-B1509/20-A-25014	2025/5/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
196	GX-B1366/25-A-25058	2025/5/20	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
197	GX-B1366/25-A-25059	2025/5/20	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
198	GX-B1366/25-A-25060	2025/5/20	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
199	GX-B1366/25-A-25056	2025/5/20	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
200	GX-B1369/20-A-25003	2025/5/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
201	GX-B1369/20-A-25004	2025/5/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
202	GX-B1364/22-A-25537	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
203	GX-B1364/22-A-25532	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
204	GX-B1364/22-A-25533	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
205	GX-B1364/22-A-25534	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
206	GX-B1364/22-A-25535	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
207	GX-B1364/22-A-25536	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
208	GX-B1364/22-A-25538	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
209	GX-B1364/22-A-25539	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
210	GX-B1364/22-A-25540	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
211	GX-B1367/22-A-25044	2025/5/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
212	GX-B1508/22-A-25006	2025/5/21	阻燃性能不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
213	GX-B1508/22-A-25005	2025/5/21	阻燃性能不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
214	GX-B1367/22-A-25045	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
215	GX-B1367/22-A-25046	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
216	GX-B1363/22-A-25293	2025/5/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
217	GX-B1363/22-A-25294	2025/5/22	所检项目合格。	 A photograph showing two men in light blue work shirts inspecting a large, dark-colored industrial machine. The machine has a large, rectangular door that is open, revealing internal components. One man is looking into the machine, while the other is looking at the door. A green trash bin is visible in the background. The date stamp '2025.05.17' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
218	GX-B1363/22-A-25287	2025/5/22	所检项目合格。	 A photograph showing two men in light blue work shirts inspecting a large, rusted industrial furnace or boiler. One man is on the left, looking at the side of the unit, while the other is on the right, wearing green gloves and looking into the open door of the furnace. A green trash bin is visible on the left. The date '2025.05.16' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
219	GX-B1366/25-A-25061	2025/5/23	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
220	GX-B1365/25-A-25054	2025/5/23	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
221	GX-B1366/25-A-25062	2025/5/23	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
222	GX-B1366/25-A-25055	2025/5/23	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
223	GX-B1364/22-A-25541	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
224	GX-B1364/22-A-25542	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
225	GX-B1364/22-A-25543	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
226	GX-B1364/22-A-25550	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
227	GX-B1364/22-A-25545	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
228	GX-B1364/22-A-25546	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
229	GX-B1364/22-A-25544	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
230	GX-B1364/22-A-25547	2025/5/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
231	GX-B1364/22-A-25548	2025/5/23	所检项目合格。	